

Larry Hogan *Governor* 

Michael J. Frenz *Executive Director* 

Members Thomas E. Kelso *Chairman* 

Leonard J. Attman Joseph C. Bryce Gary L. Mangum Manervia W. Riddick James T. Smith, Jr. Jodi C. Stanalonis

Procurement

. . . . . . . . . . . . . . . . . . .

John F. Samoryk Vice President

Maryland Stadium Authority The Warehouse at Camden Yards 333 W. Camden Street, Suite 500 Baltimore, MD 21201 410-333-1560 1-877-MDSTADIUM Fax: 410-333-1888

www.mdstad.com

Voice: 800-201-7165 TTY: 800-735-2258

## ADDENDUM No. 1 Video Replay Replacement Oriole Park at Camden Yards MSA Project No. 18-057

**Date Issued**: February 23, 2018

This Addendum is hereby made a part of the Contract Documents dated February 12, 2018 on the subject work as though originally included therein. The following amendments, additions, and/or corrections shall govern this work. <u>This form should be acknowledged below and submitted with the Invitation for Bids.</u>

This Addendum incorporates the following items:

- 1. The Pre-Bid summary along with the sign-in sheet (attached).
- 2. Questions and Answers.

Issued by:

Maryland Stadium Authority 333 W. Camden Street, Suite 500 Baltimore, MD 21201 Sandra Fox, Procurement Officer

Company

Acknowledgment (Name and Title) Date

	Pre-Bid Summary
Solicitation:	Video Replay System Replacement Oriole Park at Camden Yards MSA Project No. 18-057
Subject:	Summary from Pre-Bid Meeting February 21, 2018 at 11:30 a.m.
Bid Due:	No later than 11:00 a.m. (Local Time) on February 27, 2018
MBE Goal:	None
Written Questions:	All questions should be submitted in writing to the attention of the Procurement Officer, Sandra Fox, <u>sfox@mdstad.com</u>
MSA Attendees:	Sandra E. Fox, John Samoryk, Vince Steier, Joe March and Theresa Masilek

Sandra Fox opened the meeting with introductions and by stating the instructions for submitting bids. All Bids must be received in the Office of the Maryland Stadium Authority located at 333 West Camden Street, Suite 500, Baltimore, Maryland 21201, **no later than 11:00 a.m. on February 27, 2018.** Late, faxed, or emailed bids will not be accepted. There is not an MBE participation goal established for this procurement. Prospective bidders were urged to check the website for future addenda. It is the Bidders' responsibility to make sure they have received all appropriate documents, prior to the bid due date. All Bidders must be registered with eMaryland Marketplace in order to receive a contract award.

Bidders were advised to pay close attention to Section 4 –Bid Format. All questions must be submitted to Sandra Fox preferably by email at <u>sfox@mdstad.com</u>.

Vince Steier stated that the contractor is to replace the existing 6-channel (4-in, 2 out) video replay system in the Scoreboard Control Room in Oriole Park at Camden Yards. As stated in the scope of work, the device must be a broadcast-grade industry standard rack-mountable slow-motion playback clipping & playback operator station, operable by GUI via KVM or direct, with at least 4 channels in and 2 channels out.

Record: minimum 4 channels 1080i at 59.94 HDSDI Playback: minimum 2 channels 1080i at 59.94 HDSDI Storage: minimum 1 TB

Upon delivery of the unit, the physical installation and pre-wire will be performed by MSA. The commissioning of the unit, after it is physically installed by MSA, will be provided by the bidder as part of this contract. Training will encompass both maintenance training as well as operator training. The delivery date will determine the training date.

*February 21, 2018* at 11:30 a.m. ATTENDANCE SHEET Pre Bid Meeting

PROJECT NAME: MSA PROJECT NUMBER: FACILITY: MBE Goal:

Video Replay System Replacement 18-057 Oriole Park at Camden Yards <u>0</u>% of Total Dollar Value

Sandra Fox  $\frac{1}{2}$ , John Samoryk  $\frac{1}{2}$  Joe March  $\frac{1}{2}$ , Vince Steier  $\frac{1}{2}$ , and Theresa Masilek  $\frac{1}{2}$ . **MSA Attendees:** 

4	Company Name	Contact Name & Phone Numbers	Street Address	City/State/Zip Code	E-mail Address	Minority Business Enterprise (Yes or No)	Small Business Reserve (Yes or No)
1.	H A DESIGN	HADESIGN ED CALECA 6700 SPAMPING 703 778 8760 CENTR DUNE	6700 SPANAR	S PRULTICES	Ccelecu G HA David	0 2	Her
		EXT 116	SPANDY FRAND V.A	V 22192			
2.	HA Design Grug	HA Design Group Stave Lewis 6700 Springfield Springfield	6700 Springfield	Sprighted		200	
		Ect. 104	103110-0100 Centre Unice	72150	1ac usichan	(4)	
	CEI	Ken Miller	Ken Miller Ssoo Cluner ben of		kmill e		
;		703-550-5800	703-550-5800 Newington, UA	mpr	CO MUNENG. Con	NO	
		× 3003					
4	ter j	Spire Junes	8500 Counter every and		Signer		
:	3	no25 - 055-202	NEWIGHAN, VA 22/3		CONNERED		
					-com		

ATTENDANCE SHEET

Page 1

Small Business Reserve (Yes or No)		No Ves	
Minority Business Enterprise (Yes or No)	5.00	Let RC	gh Group ustheld Center Drive tu, Virginia 21160 att, Virginia 21160 att of www.hadesign.net leca@hadesign.net lega Group ringfield Center Drive leut, Virginia 22150 wis slewis@hadesign.net www.hadesign.net
E-mail Address	Chargebuskie everte un	Meysia ebate NO Howardevition het NO	CS19 00 Sprink to the second all effects of the second second of the second of the second of the second of the second of the second of the second of the second of the sec
City/State/Zip Code		MANASSA	Edd Call 571-215-8816 Technology/Managin/Manag
Street Address		ALL BATTENAN BUND ALL BUTTES CIT-D ALL BUTTES CIT-D PELISEVSTOUN, MU	
Contact Name & Phone Numbers		Hound Rethouse	COMMUNICATIONS Renneth D. Miller Frojet Manager B500 Cinder Bed Rind Newrigton VA 2641Rod Newrigton VA 264126 70315505180 FAX http://www.commeng.com
Company Name	Red Coderts	VPC, In.	CCOMMUNICATIONS ENGINEERING, INC. Michael R. "Spike" Jones Sales & Marking Sales & Marking Sales & Marking Sales & Marking Sales Antender Bad Road Newington: M 22122 Newington: M 22122
	°.	·•	

## **Questions and Answers**

1. Will cable changes need to be made?

We will be replacing a six-channel unit with a six-channel unit, so the HDSDI cable pathways and distribution will largely remain the same. MSA recognizes that monitoring will need to change, and cabling to the station monitors will need to be added. Also, embedding and deembedding of audio channels from the analog router will be added as needed. This work will be performed outside the Bidder's contract.

## *2.* Does the existing switch need to be upgraded?

We anticipate that the network switches in the control room, which were upgraded in 2014, are fully capable of handling Gigabit speed network traffic as needed, with 10Gb ports available to us. No replacement or upgrade of the network infrastructure is needed. MSA will handle any network configuration changes and IP assignments as needed.

3. Will all of the installation be done by MSA?

The physical installation will be performed by MSA. The setup and configuration of the software and commissioning of the unit is to be provided by the Bidder.

4. When is the completion date?

Assuming no award issues, we are hoping to receive contract approval\_on March 6, 2018. Official contract notification would occur soon after. MSA will work with the Bidder and manufacturer on an installation and training schedule that works with MSA and our stadium partner, the Orioles. We are hopeful of a project completion, including all training, by the Orioles' Opening Day on March 29, 2018.

5. What is the product you wish for? Are alternates welcomed?

The specifications are for a 6-channel Evertz Dreamcatcher replay system as listed. The bidder is permitted, however, to submit comparable voluntary alternates.

MSA notes that we do have contractual obligations to the Orioles to provide industry-standard solutions and products for the Control Room, so any voluntary alternates would have to meet that general criterion.

## 6. Could training be more than one day?

Due to the familiarity with the Dreamcatcher product line by both MSA and Orioles Productions' staff, only one (1) day of maintenance and operator training is anticipated to be needed. For any voluntary alternates, the training regimen should be per manufacturer recommendations for that product, and the training priced accordingly.

*NOTE: Please be sure to include all travel costs with any training and integration costs.*