

Image I





Image II



TYP of Raker Beam

TYP of Horizontal Beam as reference line to paint above. Horizontal beam is excluded from scope.

TYP of 2 M&T Bank Stadium Sign Support Steel




Image V



Image VI





Image VII



TYP of 4
Underside of
Upper Deck Steel

